




Connection Kits

PUREX MACHINE INLET DIAMETERS


- 40mm 2tiP
- 57mm FumeCube
- 75mm FumeBuster
- 80mm 150, 200, 400, 200i, 400i, 200i-HP, 400iPVC Alpha, Alpha Dust, Xbase, FumeCube Max, FumeSafe
- 100mm 800i
- 150mm 1500i,2000i
- 200mm 5000i



32mm Connect to 32mm diameter pipe/port 1.5m

80mm 1.5m

- Code: 100170 I x 80-34mm reducer
- I x I.5m x 41mm flexible hose
- 2 x Half straight connector
- 2 x 35-50mm hose clips





Connect

3.0m (Anti Static)


80mm

- 100026 Code:
- L x 3m x 50mm antistatic hose
- 2 x 51mm antistatic cuffs

50mm Twin Head AntiStatic


80mm

80mm



2.0m

These are bespoke kits. An example is shown on the left. Contact us for more information.




- I x earth strap 6mm
- I x 80mm to 51mm reducer

50mm

2.0m

57mm




Code: 120117

I x 2m x 51mm flexible hose

 2×5 I mm cuffs

80mm 50mm 3.0m



Code: 100032

- I x 80-51mm reducer
- Lx 3m x 51mm flexible hose
- 2 x 51mm cuffs

50mm

Connect

to 50mm

diameter

pipe/port

or Purex

6.0m

valve

6.0m

80mm

Type Code: Std 100043 100043C PVC*

- I x 80-51mm reducer
- I x 6m x 51mm flexible hose
- 2 x 51mm cuffs
- * coated reducer suitable for PVC applications

50mm 6.0m (Dual Manifold)

Connect to 50mm diameter pipe/port or Purex valve 6.0m

Code: 100039*

(Use with 100043 or 100043C)

I x dual manifold assembly(120093C)


80mm

- $1 \times 6m \times 51mm$ flexible hose
- 2 x 51mm cuffs
- * also suitable for PVC applications.

- 26 purex@purex.co.uk www.purex.co.uk



Connection Kits



hose


2.0m

0.3m

2 x 90-120mm hose clips



Connection Kits



 $2 \times 0.25 m \times 150 mm$ flexible hose

4 x 135-165mm hose clips

3.0m



Pipe & Duct


Plastic Pipe Ø 32mm		Plastic Pipe Ø 50mm		Plastic Pipe Ø 82mm	
3.0m straight pipe 500050 - Grey 500055 - Black ABS		3.0m straight pipe 520000 - Grey 520300 - Black ABS		3.0m straight pipe 530110 - Grey	
Straight connector 500060 - Grey 500065 - Black ABS		Straight connector 520020 - Grey 520330 - Black ABS		Straight connector 530170	
45° bend 500070 - Grey		45° bend 520070 - Grey		45° bend single socket 530180	
90° bend 500080 - Grey 500090 - Black ABS		90° bend 520080 - Grey 520130 - Black ABS	T ₁	90° bend single socket 530190	
Swept 'T' 500100 - Grey 500110 - Black ABS		Swept 'T' 520120 - Grey 520320 - Black ABS		Swept 'T' 530210	
End blank 500120 - Grey 500130 - Black ABS	ф	End blank 520170	Ф	Socket plug 530220	
Pipe clip 500180	Ω	Pipe clip 520180	Ω	Pipe clip 530120	Ω
		Pipe reducer (50-32mm) 520150	50 32	Pipe reducer (82-50mm) 530200	82 50
				82mm Strap boss 530160	DE
				50mm Boss adaptor 530150	111

	Steel Duct Ø 100mm	Steel Duct Ø 150mm	Steel Duct Ø 200mm
***	3.0m spiral pipe 540100	3.0m spiral pipe 540300	3.0m spiral pipe 540600
	90° bend 540133	90° bend 540345	90° bend 540620
2	45° bend 540130	45° bend 540333	45° bend 540622
9	30° bend 540129	30° bend 540328	
434	Equal 'T' 540145	Equal 'T' 540337	Equal 'T' 540630
9	End cap 540161	End cap 540400	End cap 540402
Ω	'U' bracket saddle 540190	'U' bracket saddle 540450	'U' bracket saddle 540891
	Butterfly valve 540185	Butterfly valve 540440	Butterfly valve 540439
()	Pipe reducer (100mm-80mm) 540150	Pipe reducer (150mm-100mm) 540382	Pipe reducer (200mm-150mm) 540640
50	ENERGY Valve - Alternating Shut Off (100mm) Special		ENERGY Valve - Alternating Shut Off (200mm) 540684



Arms & Accessories

38mm x IM Stainless Steel Flexible Arm Kit



Capture Apparatus Included

- 38mm x Im stainless steel flexible arm with fixed pen nib nozzle
- Support collar and valve
- I x Screwed bench bracket
- I x 51mm x 2m flexible hose with 2 connecting cuffs

Replacement parts available if required.



Capture Apparatus Included

- 38mm x 1m stainless steel flexible arm (includes I x Support collar and valve)
- Clamped bench bracket
- I x Pen-nib nozzle (38mm ID)
- I x Conical cowl (95mm ID)
- I x 51mm x 2m flexible hose with 2 connecting cuffs

Replacement parts available if required.

Code: 100294

Code: 100295

38mm Spares and Accessories

Capture Apparatus (Optional)



Clear hood cowl (265 x 310mm) Code: 840160




Pen Nib Nozzle (38mm ID) Code: 840170



Delta cowl (192 x 5mm inlet) Code: 840182



Conical Cowl (95mm ID) Code: 840190





Screwed bench bracket

Code: 840200



Clamped bench bracket

Code: 120180



Wall bracket

Code: 840210



Bench support collar and valve

Replacement 38mm x IM Stainless Steel Flexible Arm



This is a high quality stainless steel replacement arm to fit plastic push fit system arms.

- I x 38mm x Im stainless steel flexible arm
- I x Pen-nib nozzle (38mm ID) or I x Conical cowl (38mm ID)
- I x Tapered fitting



Pen Nib Type Code: 120143

Conical Cowl Type Code: 120144

Plenum Cowls



Plenum cowl Anti static polycarbonate (black) Includes 57mm airflow valve Code: 120703



Plenum cowl

Anti static polycarbonate (clear) Includes 57mm airflow valve Code: 120704




Max W x L 300 x 400mm


Connection kits with 51mm cuffs are suitable for 57mm valves



Arms & Accessories


CleanCab Enclosed Extraction Unit







Complete Kit



Includes:
Base
Open Hood
57mm Airflow valve
Code: 840150


Hood Only




Includes: Open Hood 57mm Airflow valve Code: 840159

Includes:

Base Code: 840152




Includes: Base Open Hood 75mm Exhaust port Code: 840155




Includes: Open Hood 75mm Exhaust port Code: 840171



Includes:
Downdraught Base
Perforated steel plate
Code: 840161



Downdraught Base Perforated steel plate Open Hood Code: 840164



Includes: Open Hood Code: 840151



Connection kits with 51mm cuffs are suitable for 57mm valves - for 75mm exhaust port use kit 100185

Clean Air Feed

Free Clean Air!

 Purex machines produce very clean air from the exhaust so why not use it?

 This replacement exhaust cowl can be used to supply clean air to equipment such as lasers, ovens and more...

 Machine Range:
 Code:

 200/400, 200i/400i
 190040

 800i
 190039

 1500i/2000i
 640002



Dual Inlet Manifold

Connect two hose to one machine.

Manifold: Code:
Aluminium Manifold 120093
Coated Aluminium Manifold 120093C

for corrosive fumes.

(1 x 80mm to 2 x 50mm inlets)



Large Flexible Arms - Call



Compressors

30 PSI / 2.1 bar

Compressor: Code: Free standing 100284 Integrated* 100283

* 200i/400i/Alpha/Xbase



www.purex.co.uk - 31 - purex@purex.co.uk



Tip Kits & Accessories

Universal - Soldering Iron Kit

Allows an extraction tube to be fitted to most common soldering irons.

- I x I.5m x 6mm ID x I.5mm wall clear silicone hose (560030)
- I x screw in adaptor (8mm hose, M10) (580010)
- 2) 3) 5 x 8mm Ø hose clips (580525)
- 4) I x universal iron stand (830007)
- 5) I x soldering iron stand (830008)
- 6) I x cup standard iron (830000)
- 7) I x cup metcal iron (830005)
- I x extraction tube clip weller (830040) 8)
- 9) I x extraction tube clip metcal/mini weller (830050)
- I x extraction tube clip universal (830065) 10)
- I x 6mm Ø x 100mm extraction tube weller (830110) H)
- 12) I x 6mm Ø x I35mm extraction tube metcal (830112)
- I x 6mm Ø x 225mm extraction tube universal (830135) 13)





Specific - Soldering Iron Kits

Allows an extraction tube to be fitted to specific soldering irons.

Metcal iron kit	100075
I x extraction tube clip	830050
I x 6mm Ø x 135mm extraction tube	830112
I x 1.5m x 6mm ID x 1.5mm wall	560030
clear silicone hose	
5 x hose clips	580525
Universal iron stand	830007
I x screw in adaptor (MI0)	580010



Large Weller iron adaptor kit	100070
I x extraction tube clip	830041
1 x 7mm Ø x 150mm extraction tube	830115
I x I.5m x 6mm ID x I.5mm wall	560030
clear silicone hose	
5 x hose clips	580525
I x soldering iron stand	830008
I x cup	830002
I x screw in adaptor (MI0)	580010



Antex/Ersa iron kit	100085
I x extraction tube clip	830050
I x extraction tube clip	830065
I x 6mm Ø x 225mm extraction tube	830135
I x I.5m x 6mm ID x I.5mm wall	560030
clear silicone hose	
5 x hose clips	580525
Universal iron stand	830007
1 x screw in adaptor (M10)	580010



Pace iron adaptor kit	100072
I x extraction tube clip	830065
I x 6mm Ø x 100mm extraction tube	830110
I x I.5m x 6mm ID x I.5mm wall	560030
clear silicone hose	
5 x hose clips	580525
I x soldering iron stand	830008
I x cup	830002
I x screw in adaptor (MI0)	580010



Mini Weller iron kit	100065
I x extraction tube clip	830050
I x 6mm Ø x 135mm extraction tube	830112
I x 1.5m x 6mm ID x 1.5mm wall	560030
clear silicone hose	
5 x hose clips	580525
I x soldering iron stand	830008
I x cup	830005
I x screw in adaptor (MI0)	580010



Hakko iron adaptor kit	100030
2 x extraction tube clip	830050
I x 6mm Ø x 225mm extraction tube	830136
1	



Adcola iron kit	100060
I x extraction tube clip	830040
I x 6mm Ø x 100mm extraction tube	830110
I x I.5m x 6mm ID x I.5mm wall	560030
clear silicone hose	
5 x hose clips	580525
I x soldering iron stand	830008
I x cup	830000
I x screw in adaptor (MI0)	580010





Tip Kits & Accessories

These optional kits allow the user to quickly and simply detach the soldering iron from the extraction system. The options are:

- To detach the iron from the main pipework.
- To detach the iron from trunking on the bench.
- To detach the iron from an ON/OFF tap.

Use with Soldering Iron Kits shown on previous page.

Optional - Trunking Connector Kit (Quick Release)				
I x Adaptor tube 8mm x 65mm	(580300)		4	
I x 8mm red blank	(580130)		Connect extraction — — — Trunking tube from soldering iron	
I x Trunking connector (8mm)	(580190)			
I x 8mm Connector hose stem	(580210)	AND THE WAY		
I x I.5m x 6mm ID x I.5mm wall clear silicone hose	(560030)	edicalis		
I x screw in adaptor (8mm hose, MI0)	(580010)			
Code: 100090			PIPE	

I x 8mm Connector hose stem I x 0.04m x 8mm ID x 2mm wall clear silicone hose I x ON/OFF tap bracket 4 x Screws I x ON/OFF tap I x Im x I 3mm flexihose 2 x Hose clip I 5mm I x Adaptor I 2mm hose 3/8BSP	(580210) (560060) (580090) (580080) (570000) (580500) (580035)	ap Kit (Quick Relea	Connect extraction tube from soldering iron
---	--	---------------------	---

Optional - Tube Cleaning Brushes				
Tube cleaning brushes				
5mm bronze	830200			
Airflow meter				
5-50 I/min	330200			
10-100 I/min	330201			



Machine Interfacing

4 way Mini Bulgin



Code: 105097 (5M cable)

ALARM

PINS I + 2 = VOLT FREE ALARM OUTPUT CONTACTS

REMOTE START

VOLT FREE CONTACTS REQUIRED TO OPERATE PIN 3 = REMOTE START INPUT SIGNAL PIN 4 = +12V DC

5 way XLR Neutric



Code: 105105 (5M cable)

PINS I + 4 = VOLT FREE ALARM OUTPUT CONTACTS

REMOTE START

VOLTAGE SIGNAL REQUIRED TO OPERATE PIN 2+3 (LINKED) = REMOTE START INPUT SIGNAL PIN 5 = 0V DC

6 way Bulgin



Code: 105103 (5M cable)

PINS I + 4 = VOLT FREE ALARM OUTPUT CONTACTS

REMOTE START

VOLT FREE CONTACTS REQUIRED TO OPERATE PIN 3 = REMOTE START INPUT SIGNAL PIN 5 = +12V DC

PIN 2 + 6 = NOT USED

9 way D-type



Code: 105106 (5M cable)

ALARM

NO ALARM OUTPUT

REMOTE START

VOLTAGE SIGNAL REQUIRED TO OPERATE PIN 2 = 0V DC PIN 3 = +12VDC / +24VDC REMOTE START INPUT SIGNAL

9 way D-type



Code: 105107 (5M cable)

ALARM

PIN 3 = +12VDC / +24VDC ALARM OUTPUT

REMOTE START

VOLTAGE SIGNAL REQUIRED TO OPERATE PIN I = REMOTE START INPUT SIGNAL PIN 9 = 0V DC

9 way D-type



Code: 105104 (5M cable)

ALARM

PINS I + 2 = VOLT FREE ALARM OUTPUT CONTACTS

REMOTE START

VOLT FREE CONTACTS REQUIRED TO OPERATE PIN 3 = REMOTE START INPUT SIGNAL PIN 4 = +12V DC

6 way Lumberg



Code: 105096 (5M cable)

PINS I + 6 = VOLT FREE ALARM OUTPUT CONTACTS PINS 3 + 4 = VOLT FREE ALARM OUTPUT CONTACTS

REMOTE START

VOLTAGE SIGNAL REQUIRED TO OPERATE PIN 5 = +12VDC / +24VDC REMOTE START INPUT SIGNAL

PIN 2 = 0V DC INPUT

7 way Lumberg



Code: 105098 (5M cable)

PINS 3 + 4 = VOLT FREE ALARM OUTPUT CONTACTS

REMOTE START

VOLTAGE SIGNAL REQUIRED TO OPERATE PIN I = +12VDC / +24VDC REMOTE START INPUT SIGNAL

PIN 2 = 0V DC INPUT PIN 5 + 6 = LINKED

PIN 7 = NOT USED

No Connector




Code: 105108 (5M cable)

Yellow and green wires = remote start stop Volt free contacts required to close these wires to start (+12VDC signal)

Red and blue wires = alarm signal Output via a set of volt free contacts inside Purex

Remote ON/OFF **Switch**



Code: 105114 (5M cable)

Now you can easily switch your Purex fume extractor on or off from up to 5m away. This is particulary useful if your fume extractor is tucked away under a bench or in a cupboard where it cannot easily be accessed. This feature is also useful if the work you do is not continuous e.g. intermittent hand soldering as you will be saving energy by turning the extractor off.



Power Plug Options

Note: A plug will be supplied to match the destination region on the order. E.g. an order to go to the UK will be supplied with a UK plug unless you request otherwise.

FumeCube (inc MAX), FumeBuster, FumeSafe, 2tiP and Captivair

Are supplied with a 2m long detachable cable with a choice of plug.

USA/ASIA 120V	UK	Europe	No Plug
			Bare wire only.
Code: 410125	Code: 410100	Code: 410127	Code: 410120

150, 200/400, 200i/400i, 400iPVC, Alpha, Xbase

Are supplied with a 5m long detachable cable with a choice of plug.

Code: 410165

USA/ASIA 120V	USA/ASIA 230V	UK	Europe
Code: 410160	Code: 410161	Code: 410162	Code: 410163
Australia	No Plug		
	Bare wire only.		

800i, 1500i, 2000i, 5000i

Code: 410164

Are factory fitted with a 5m long cable without a plug.

Electrical installations should only be carried out by a qualified person.